

Measurements


Sp1	69.7 °F
-----	---------

Parameters

Emissivity	0.95
Ref. temp.	68 °F


ELECTRIC RADIANT FLOOR HEATING EASILY SEEN AND FUNCTION VERIFIED

8/17/2019 4:21:43 PM



ELECTRIC RADIANT FL... FLIR E8 Wifi 639045830

8/17/2019 4:21:43 PM



ELECTRIC RADIANT FL... FLIR E8 Wifi 639045830


Measurements

Sp1	75.6 °F
-----	---------

Parameters

Emissivity	0.95
Ref. temp.	68 °F

10/2/2019 12:07:27 PM



HYDRONIC RADIANT F... FLIR E8 Wifi 639045830


HYDRONIC RADIANT FLOOR HEATING

THERMOSTAT OFF UPON ARRIVAL

THE RIGHT PIPE IS THE RETURN LINE FROM THE LIVING ROOM HEATING ZONE

SYSTEM FUNCTION VERIFIED & IN-FLOOR HEATING LINES LOCATED

10/2/2019 12:07:27 PM



HYDRONIC RADIANT F... FLIR E8 Wifi 639045830

Measurements

Sp1	71.5 °F
-----	---------

Parameters


Emissivity	0.95
Ref. temp.	68 °F

HYDRONIC FLOOR HEATING

THERMOSTAT OFF UPON ARRIVAL

SYSTEM FUNCTION VERIFIED & IN-FLOOR HEATING LINES LOCATED

10/2/2019 12:08:01 PM



HYDRONIC RADIANT F...

FLIR E8 Wifi

639045830

10/2/2019 12:08:01 PM



HYDRONIC RADIANT F...

FLIR E8 Wifi

639045830

Measurements

Sp1	58.6 °F
-----	---------


Parameters

Emissivity	0.95
Ref. temp.	68 °F

INSULATION PROBLEM

FIBERGLASS BATTING HAD
FALLEN AWAY FROM THE OTHER
SIDE OF THE WALL

10/31/2019 10:42:19 AM




INSULATION PROBLEM...

FLIR E8 Wifi

639045830

10/31/2019 10:42:19 AM



INSULATION PROBLEM...

FLIR E8 Wifi

639045830


Measurements

Sp1	50.1 °F
-----	---------

Parameters

Emissivity	0.95
Ref. temp.	68 °F

10/8/2019 4:54:32 PM




NO THERMAL ANOMOLIES - WALL IS WELL INSULATED

INSULATION GOOD.jpg

FLIR E8 Wifi

639045830

10/8/2019 4:54:32 PM



INSULATION GOOD.jpg

FLIR E8 Wifi

639045830


Measurements

Sp1	58.9 °F
-----	---------

Parameters

Emissivity	0.95
Ref. temp.	68 °F

8/8/2019 10:35:12 AM



AC & DUCT CHECK.jpg

FLIR E8 Wifi

639045830

AIR CONDITIONING

TEMPERATURE & AIR FLOW
VERIFICATION

8/8/2019 10:35:12 AM



AC & DUCT CHECK.jpg

FLIR E8 Wifi

639045830




Measurements

Sp1	123.5 °F
-----	----------

Parameters

Emissivity	0.95
Ref. temp.	68 °F

8/8/2019 12:38:21 PM



HEAT & DUCT CHECK.jpg

FLIR E8 Wifi

639045830

HEATING SYSTEM

TEMPERATURE & AIR FLOW
VERIFICATION

8/8/2019 12:38:21 PM



HEAT & DUCT CHECK.jpg

FLIR E8 Wifi

639045830

Measurements

Sp1	155.0 °F
-----	----------


Parameters

Emissivity	0.95
Ref. temp.	68 °F

BASEBOARD HEATING

TEMPERATURE & OPERATION
VERIFICATION

10/21/2019 11:31:15 AM



ELECTRIC BASEBOAR...

FLIR E8 Wifi

639045830

10/21/2019 11:31:15 AM



ELECTRIC BASEBOAR...

FLIR E8 Wifi

639045830